


2004 Honda Civic LX

Fig. 10: Identifying Connector To Harness (Engine Compartment Wire Harness (Left Branch) (2-door) - 1 Of 2)

Courtesy of AMERICAN HONDA MOTOR CO., INC.



G01412805

© 2006 Mitchell Repair Information Co., LLC.