


2003 Honda Civic LX - Fig. 94: Instrument Cluster Circuit, EX, HX, LX (2 of 2)



© 2006 Mitchell Repair Information Co., LLC.